

PEDESTRIAN MOVEMENT SURVEY

Road Name / No.	Start Location (car park, housing estate, road) : Name & OS grid ref.	End Location (in town): Name & OS grid ref.
Millpond Street	Kings Acre Car Park: (Lower) OS	Brookend Street OS
Signage towards town (follow-able)	Close to town but not obvious, Ross black signpost nearby but does not list "To town" as a direction. FAILED Photos Millpond Street (1) & (2).	
Pavement surface condition (Loose, broken) (Obstacles) (Wheelchair issues – steps) (Buggy issues – width for double)	Car park surface – excellent Pavement block sets, some attention needed to re-level in Brookend Street Brookend Street pavement just wide enough for a wide double buggy or mobility scooter.	
Dangers (cyclists - using pavement) (obstacles from sides – brambles, nettles, pieces of metal) (Vehicles on pavement) (Crossing busy road)	Millpond Street road crossing at Five Ways busy with vehicles approaching from multiple directions. Kerbs lowered at obvious marked crossing location, visibility good.	
Lighting during day (eg. In covered passageways)	No problems	
Lighting at night (Enough for safety) (Blinding light ahead)		
Ambience (Views of bins / rubbish) (Bad smells) (Cleanliness – rubbish or glass on floor)	Car park good, Three attractive flower containers near car park entrance. Five ways pedestrian crossing noisy Rubbish in alleyway in Brookend Street unsightly and smelly, See photos: Brookend Street (1) & (2)	
Signage away from town (back to car park)	None, but distance too far	
Other Thoughts	Overall an attractive car park and route into town, View of Morrison's unattractive expansive car park could be hidden. Rubbish in alley could be hidden behind solid gate	
Assessment	Date & Time Tuesday 20 th September 2016, 15:30	Weather Sunny