

## PEDESTRIAN MOVEMENT SURVEY

|   |   |   |
|---|---|---|
| Road Name / No.   | Start Location (car park, housing estate, road) : Name & OS grid ref.   | End Location (in town): Name & OS grid ref. |
| Over Ross Street<br>B4234   | Kings Acre Car Park: (Upper)<br>OS  | Brookend Street<br>OS                       |
| Signage towards town<br>(follow-able)   | Ross town wall map showing where town is, faded but OK<br>One signpost to town - too faded to read on either side.<br>See photo: Over Ross Street   |   |
| Pavement surface condition<br>(Loose, broken)<br>(Obstacles)<br>(Wheelchair issues – steps)<br>(Buggy issues – width for double)                        | Car park surface - patched tarmac, poor quality<br><br>Pavement along Ledbury road - patched tarmac and concrete.<br><br>Also see pedestrian survey page for Millpond Street              |   |
| Dangers<br>(cyclists - using pavement)<br>(obstacles from sides – brambles, nettles, pieces of metal)<br>(Vehicles on pavement)<br>(Crossing busy road) | See pedestrian survey page for Millpond Street  |   |
| Lighting during day<br>(eg. In covered passageways)   | No problems   |   |
| Lighting at night<br>(Enough for safety)<br>(Blinding light ahead)  |   |   |
| Ambience<br>(Views of bins / rubbish)<br>(Bad smells)<br>(Cleanliness – rubbish or glass on floor)  | Car park ambience ruined by poor surface, and view of garage business, view of metal containers at rear of carpet showroom and un-kept vegetation. See photos: Kings Acre CP (1) – (6)    |   |
| Signage away from town<br>(back to car park)  | None.   |   |
| Other Thoughts  | Ambience could be improved with fencing to hide business and vegetation. Town map should be replaced and town plan holder reconditioned. Signpost to town centre needs urgent replacement |   |
| Assessment  | Date & Time<br>Tuesday 20 <sup>th</sup> September 2016, 15:30   | Weather<br>Sunny                            |